Under Review Notification

Raised By: Vanessa Morel Product #: RB GT1-90007441000

Date: 2019.11.05 Product Name: OIL COOLER DRIVE SHAFT NUT TORQUE SOCKET

		"Y" or "N" Required for Each Part Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	¥	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RB GT1-90007441000	RB GT1-90007441000 Rev	Υ	Υ	N	Υ	Υ	N	N	N	19-1199	See below

Description of Issue:

Issues stated on ADR (Napkin drawing)

RB GT1-90007441000 must be put on HOLD in Plex

RB GT1-90007441000 Finish good stock can be use as is

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations

Chief Engineer

Customer Support Manager

Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene